

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20201756
Address: 1521 SW SUGAR TREE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Patrick Schonfeldt	Failed	Thursday, October 29, 2020

Corrective Action Required:

1	Misc	-horizontal blocking shall be placed between studs at the door lock height for 3 stud spaces or equivalent bracing on each side of exterior door openings - security blocking back door -Plan calls double every other 2 x 10 from master bedroom steel beam to garage/dwelling separation wall -Flash exterior windows -6" OC edge and 12" OC field exterior sheathing fastening
---	------	--

OK TO INSULATE, REMOVE ANY INSULATION FROM INSPECTION ITEMS

Comments: