



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20202426, Public Works Right of Way Permit

Address: 207 SE DOUGLAS ST, LEES SUMMIT, MO 64063209 SE DOUGLAS ST, LEES SUMMIT, MO 64063110 SE 3RD ST, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Passed	Thursday, October 29, 2020

Corrective Action Required
1

Site visit: ECC requested to close this permit. I did a walk through of the alley according to the map that was attached. All work is completed, the core holes have been filled.

Comments: