



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20203531, Public Works Right of Way Permit
Address: 4399 SW AMETHYST DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Passed	Tuesday, November 10, 2020

Corrective Action Required

1 Misc

Site visit: It appears the work has been completed. The piping to where the meter would sit has been installed. This is an active home build site. Grass vegetation was not established prior to Spires work.

Comments: