



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20203621, Public Works Right of Way Permit  
Address: 1840 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Passed	Thursday, November 19, 2020

**Corrective Action Required**

1      Misc

Site visit: The gas service has been installed at the home. This is a new home build site, the grass was not established prior to Spires work. There was a sidewalk panel that was taken out and put back across the street from the home.

**Comments:**