## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRSUBD20202246 Address: 1195 NW VIEW HIGH DR, LEES SUMMIT, MO 6408111904 NW CHIPMAN RD, LEES SUMMIT, MO 6408111800 NW CHIPMAN RD, LEES SUMMIT, MO 6408111906 NW CHIPMAN RD, LEES SUMMIT, MO 640811201 NW VIEW HIGH DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection:                             |        | Inspector:   | Outcome:   | Date:  |  |
|---|--------|--|--|--|--|
| Water Line - Construction<br>Inspection |        | John Jackson   | Partial  | Thursday, December<br>03, 2020   |  |
| Informat                                | ional: |  |  |  |  |
| 1                                       | Misc   | 9/28/20 Tuesday  |  |  |  |
|   |        | Contractor continued to in   | nstalled 12" Certa - Lok Wat   | er main Line A.  |  |
| Informational:                          |        |  |  |  |  |
| 2                                       | Misc   | 9/30/20 Wednesday  |  |  |  |
|   |        | Bends were installed @ a<br>not have to install (4) 45 [<br>Contractor will submit all | of 12" Certa - Lok Water mai<br>pproximately 16+00 and 17-<br>Deg. Bends to get the grade<br>field changes on As-Built. C<br>pe onsite on 10/02/20 Frida | +25. The contractor did<br>depth for the water line.<br>Contractor believes 10 |  |
| Informat                                | ional: |  |  |  |  |
| 3                                       | Misc   | feet more 9/30/20.<br>Today contractor installed<br>Bend, 12" Butterfly Valve          | stall 12" water main to Sta 1<br>d approximately 63' of 12" w<br>for Air Relief Assembly. Co<br>d hydrants. Contract continu<br>n on 10/2/20.            | vater main with a 22.25<br>ntractor poured thrust                              |  |
| Informational:                          |        |  |  |  |  |
| 4                                       | Misc   | 10/2/20 Friday   |  |  |  |

|          |        | Contractor continued to install 12" water main, hydrant was set @ Sta.<br>20+54.86.  |
|----------|--------|--|
|          |        | Approximately 274' of 12" Certa - Lok on Line A. Contractor working on boring pit for direction boring.  |
| Informat | ional: |  |
| 5        | Misc   | 10/6/20 Tuesday<br>Contractor continued to bore across the I-470 Hwy since yesterday 10/5/20.<br>Contractor put together 360' on the North side of I-470 Hwy for installment in<br>casement under Hwy.<br>Today 320' was install from the South side of Hwy on Line A.   |
| Informat | ional: |  |
| 6        | Misc   | 10/7/20 Wednesday  |
|          |        | Contractor continued to installed 12 Certa-Lok water main on Line A as-per<br>plan. The contractor ran into heavy rock and was only able to install 20' of<br>pipe & a fire hydrant. Continued boring across<br>I -470 Hwy.  |
| Informat | ional: |  |
| 7        | Misc   | 10/8/20 Thursday<br>Contractor was only able to install 100' of 12" Certa-Lok water main due to<br>the heavy rock in excavated area. Boring continued.   |
| Informat | ional· | the neavy lock in excavated area. Borning continued.   |
| 8        | Misc   | 10/9/20 Friday   |
|          |        | Contractor installed 126' of 12" Certa-Lok water main just beyond the 22.5<br>deg Bend @<br>Sta 29+49.08. The vertical 45 deg Bends were not needed to make the grade.<br>Contractor began to break grade at the 45 deg Bend @ Sta 28+38.83. Changes<br>to the project plans will be reflected on as-built.  |
| Informat | ional: |  |
| 9        | Misc   | 10/12/20 Monday  |
| -        |        | Contractor worked 10/10/20 progress was slow due having to fill in low<br>elevation areas as per plan.<br>Contractor continued to work on water main, thrust blocks were poured<br>behind fittings and bends.  |
| Informat | ional: | -  |
| 10       | Misc   | 10/13/20 Tuesday<br>Contractor add a crew to begin installation of 12" water main on line o the<br>Northside of I-470 Hwy. Approximately 100' of Certa - Lock 12" water was<br>installed on site on the Northside. The Southside crew was only able to<br>install 70' of 12" water main because of the rock. Southside crew continued<br>to move toward Sta. 30+69.58 were the North & West 12" Butterfly valves are<br>to be installed. |
| Informat | ional: |  |
| 11       | Misc   | 10/14/20 Wednesday   |
|          |        | Contractor of Clarkson Const. on the Northside installed 4/45 Degree Bends<br>and framed the wire<br>casing for concrete to encase vertical piping. Contractor on the Southside still<br>jackhammering rock progress is slow.2/12" Butterfly Valves were installed<br>with 12"x12" x12" Tee 6 thrust blocks was poured on Bends and Fittings.  |
| Informat | ional: |  |
| 12       | Misc   | 10/15/20 Thursday  |

|             |         | Boring operations of continued. The water line construction is at a temporarily on hold until casing are installed (and or ) until Traffic permits and sign is in place to resume further installation. |
|-------------|---------|---|
| Information |         |   |
| 13          | Misc    | 10/16/20 Friday   |
|             |         | Contractor continued to install Certa-Lock water line Consturtion on the  |
|             |         | Northside of I-470 Hwy.   |
|             |         | From approximately Sta 38+00 to 40+84 @ 2:00PM today. Contractor continue   |
|             |         | to prep for more pipe installation. Contractor said they plan to work on  |
|             |         | 10/17/20 Saturday.  |
| Information | onal:   |   |
| 14          | Misc    | 10/17/20 Saturday   |
|             |         | Contractor is preparing water line to install up to Sta 46+00. Contractors will   |
|             |         | install Certa -Lock 12" piping to Sta 45.04.70 12X12X12 Tee they will stop there  |
|             |         | because a one of the 12" valve is inoperable. So instead of closing off the   |
|             |         | entrance since they will not be able to install 12" Butterfly valve he began to   |
|             |         | backfill. Onsite supervisor of Clarkson ( Nick Peeles ) has informed his  |
|             |         | supervisor of the valves needed to continue water main installation.  |
| Informatio  | onal:   | ·   |
| 15          | Misc    | 10/19/20 Monday   |
|             |         | Contractor poured thrust blocks behind all fits and bends that were installed   |
|             |         | on Saturday. Boring began to wield encasement for water pipe that is to be  |
|             |         | installed across !-470 Hwy. South crew began to excavate to install water line  |
|             |         | that travels along NE Chipman Road.   |
| Informatio  | onal:   |   |
| 16          | Misc    | 10/21/20 Wednesday  |
| -           |         | Contractor has continued to work to get boring encasement across I-470 and  |
|             |         | continued to work to install water main.  |
| Informatio  | onal:   |   |
| 17          | Misc    | 10/22/20 Thursday   |
|             |         | the crew on the North end help to aid pulling the encasement and piping   |
|             |         | across I-470 also work was done on site for the Water Main approximately  |
|             |         | 400 was installed from the Tee. The South crew has installed 12" Water  |
|             |         | Certa-Lock pipe along relocation of water was done to not conflict with   |
|             |         | existing main. All changes shall be reflected on as-built.  |
| Informatio  | onal:   |   |
| 18          | Misc    | 10/26/20 Monday   |
|             |         | Contractor crew on the Southside did work on Saturday but they didn't install   |
|             |         | pipe backfilled and graded. Today they installed 12" Certa - Lock water main  |
|             |         | pipe along Chipman Line A. The Northside Installed approx 200' of 12" water   |
|             |         | main  |
|             |         | (This portion of the WATER MAIN falls under PRSITE 20203248)  |
|             |         | Sta. 03+97 Line D.  |
| Informatio  | onal·   |   |
| 19          | Misc    | 10/27/20 Tuesday  |
| 15          | IVII SC | Contractor Crew continued to work installation of Water Main on Chipman   |
|             |         | Road. Crew to the North backfilled excavation of boring across I-470 Hwy.   |
| Informatio  | onal·   | Noad. Crew to the North backfilled excavation of borning across 1-470 MWy.  |
| 20          | Misc    | 10/28/20 Wednesday  |
| 20          | IVIISC  | Contractor installed approximately 40' of 12" water main along Chipman  |
|             |         | Contractor instance approximately 40 of 12 water main along cmpfildh  |

|                | Road. Contractor had to cut through existing drive way to install pipe and also  |
|----------------|--|
| Informational: | clear existing 6" water main.  |
| 21 Misc        | Tie-in was complete for the existing 8" to the newly installed 12" water main.<br>12" valve head East was moved to the newly installed Northbound an<br>existing 8" valve East was less than a hundred feet away from the tie-in. A 8"<br>sleeve was add during the tie-in. Contractor will reflected any changes on<br>as-built.  |
| Informational: |  |
| 22 Misc        | 10/31/20 Saturday  |
|                | Two crews were working on the off-site 12" water main installation<br>yesterday and today. 10/30/20 The second crew installed 160' of 12" water<br>main used a 11 1/4 bend instead of 22 1/2 bend because the grade was<br>achieved before to line up with the Bore tie-in on the Southside of I-470<br>Hwy.<br>A 12" sleeve was need just 4' from the end of bore encasement, as-built will<br>reflect all field changes. 10/31/20 This crew poured thrust & straddle blocks<br>as shown on plan and backfilled excavation. 10/31 The crew on Chipman |
|                | Road progress was slow due to the existing water main and the rock that was jackhammered and excavated.  |
| Informational: | Jackhammered and excavated.  |
| 23 Misc        | 11/2/20 Monday   |
|                | Contractor installed Hydrant and approximately 80' of 12" line on Chipman Road.  |
| Informational: |  |
| 24 Misc        | 11/10/20 Tuesday   |
|                | Contractor has been locating leaks on the Northside of I-470 Hwy.  |
| Informational: |  |
| 25 Misc        | 11/11/20 Wednesday<br>Contractor working to ensure all leaks were eliminated leaks were caused<br>from the Northside crew not tightening bolts at the MJ fittings (new crew<br>members). Contractor will began pre-test pressure test.   |
| Informational: | members). contractor win began pre-test pressure test.   |
| 26 Misc        | 11/12/20 Thursday  |
|                | Contractor continue to work on water line.   |
| Informational: |  |
| 27 Misc        | 11/18/20 Wednesday<br>Contractor has concrete schedule to complete encasement of water main &<br>reinforcing steel Line A 36+80 to 37+40 (see water main detail page 10/15).   |
| Informational: |  |
| 28 Misc        | 11/19/20 Thursday  |
|                | Contractor ( Clarkson Const. ) chlorinated the water 12" Certa-Lock water<br>main from the offsite to onsite approximately 4000'. Contractor will continue<br>to backfill encasement of water main & reinforced steel section, also rough<br>grade area to reconstruct exist creek.  |
| Informational: |  |
| 29 Misc        | 11/20/20 Friday<br>Contractor de chlorinating line 12" Certa-Lock water main from the offsite to<br>onsite.  |
| Informational: |  |
|                |  |

| 30         | Misc  | 12/1/20 Tuesday began 12" Certa-Lock water main View High Drive.  |
|------------|-------|---|
| Informatio | onal: |   |
| 31         | Misc  | 12/2/20 Wednesday contractor installed 22.5 bend @ Sta. 45.94.98 instead 45 deg bend to enable the hydrant @ Sta. 46+08.09 to be installed the correct distance from back of curb. Approximately 260' was installed on Line A ( along View High Drive. Changes in elevation occurred do to survey error all field changes shall be reflected on as built. |
| Informatio | onal: |   |
| 32         | Misc  | 12/3/20 Thursday Contractor continued to install 12" Certa-Lock water line approximately 180'.  |

## **Comments:**