CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20202637 Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Footing Inspection - Commercial		Robb Popp	Partial	Tuesday, December 08, 2020
Corrective 1	e Action Required: THE FOLLOWING AREAS ARE APPROVED	2/G, 2/C, 2/D, 2/E, 2/F, 2/F 3/F, 3/G, 3.1/H, 3.1/J, 3.2/G 4/J, 4/G, 4/H, 4/H.6, E.4/H. -GRADE BEAM: LINE A.2 FR A.3 TO C, LINE 1 FROM E T E FROM 1 TO 2, LINE G FRO	L/A.2, 1/C, 1.1/C, 1.1/E, 1/E, 4, 2/J, 3/A.2, 4/A.2, 4/F, 5/A. C, 3.2/D, 3.2/E, 3.2/E.3, 3.2/C 6, 5/C, 5/D, 5/E, 5/E.3 5/F, 5 ROM 1.1 TO 5, LINE A.3 FROM O G , LINE C FROM 1 TO 2, LI M 1 TO 2, LINE 2 FROM G TO E H.6 FROM 4 TO 5, LINE 5 F	2, 3/C, 3/D, 3/E, 3/E.3, 5, 4/C, 4/D, 4/E, 4/E.3, /H.6 M 1 TO 1.1, LINE 1 FROM NE 2 FROM C TO E, LINE D J, LINE J FROM 2 TO 4,
			6/D, 6/E, 6/F, 6/H.6, 7/B, 7// .2 TO B, B FROM 6 TO 7, 7 FR	

Comments: