

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20201531  
Address: 4399 SW AMETHYST DR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Patrick Schonfeldt	Failed	Friday, December 11, 2020

Corrective Action Required:

1	Misc	-Truss hangers per plans-garage -Terminate and secure NM at basement bed hall ceiling -protection plate at top plate furred down, basement bed closet -Fireblock between top plate and framing in basement, seal all gaps and penetrations in Fireblock -Fireblock vertical every 10' between framing/foundation in basement, seal all gaps and penetrations in Fireblock -Bocca protection plates at DWV wet bar basement
---	------	---

Comments: