

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20202637
Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|--|------------|----------|---------------------------|
| Footing Inspection - Commercial | Robb Popp | Partial | Friday, December 11, 2020 |

Corrective Action Required:

| | | |
|---|----------------------------------|--|
| 1 | THE FOLLOWING AREAS ARE APPROVED | **AREA "A"*** -COMPLETE- |
| | | **AREA "B"*** -COLUMN PADS: 6/B, 6/C, 6/D, 6/E, 6/F, 6/H.6, 7/B, 7/A.2, 7/C, 7/D, 7/E, 7/F, 7/G, 8.2/A.2, 8/E.3, 8/F, 8/G, 8.1/H, 8.2/E, 8.2/E.3, 8.2/G, 9/A.2, 9/E, 9/E.3, 9/G, 9/H, 10/A.2, 10/B, ELEVATOR PIT AND PIER AT 9/D -GRADE BEAMS: 6 FROM A.2 TO B, B FROM 6 TO 7, 7 FROM A.2 TO B, A.2 FROM 7 TO 9, LINE 6 FROM H.6 TO. H, LINE A.2 FROM 9 TO 10, LINE 10 FROM A.2 TO B |
| | | **AREA "C" ** -COLUMN PADS: 10/H.6, 10/H -GRADE BEAMS: LINE H6.3 AREA B CLOCKWISE TO H10.4 |

Comments: