CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192096

Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Above Ceiling Inspection Michael Harkins Partial Monday, December 14,

2020

Corrective Action Required:

1 SECOND FLOOR - SECTION E PHASE 1 JOIST HANGERS CORRIDOR & DECKS -

CORRIDOR 219 ABOVE GRID CORRIDOR 222 ABOVE GRID CORRIDOR 226 ABOVE GRID CORRIDOR 229 ABOVE GRID

Corrective Action Required:

2 THIRD FLOOR - SECTION E PHASE 1 JOIST HANGER CORRIDOR & DECKS -

CORRIDOR 319 ABOVE CEILING GRID CORRIDOR 322 ABOVE CEILING GRID CORRIDOR 326 ABOVE CEILING GRID CORRIODR 329 ABOVE CEILING GRID-

Corrective Action Required:

3 FOURTH FLOOR - SECTION E PHASE 1 JOIST HANGERS CORRIDOR -

ABOVE CEILING GRID CORRIDORS CORRIDOR 419,422,423,426,429

- 417 AMENITY DECK ROOM ABOVE CEILING OK TO COVER -

Corrective Action Required:

4 FIRST FLOOR - LOWER LEVEL LOBBY SOUTH MECH ROOM ABOVE CEILING OK TO COVER -

- CORRIDOR 119 ABOVE CEILING GRID -
- CORRIDOR 122 ABOVE CEILING GRID -
- CORRIDOR 129 ABOVE CEILING GRID -

Comments: