## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20202637

Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Footing Inspection - Robb Popp Partial Monday, December

Commercial 14, 2020

Corrective Action Required:

1 THE FOLLOWING \*\*AREA "A"\*\*
AREAS ARE -COMPLETE-

APPROVED

\*\*AREA "B"\*\*

-COLUMN PADS: 6/B, 6/C, 6/D, 6/E, 6/F, 6/H.6, 7/B, 7/A.2, 7/C, 7/D, 7/E, 7/F, 7/G, 8.2/A.2, 8/E.3, 8/F, 8/G, 8.1/H, 8.2/C, 8.2/D, 8.2/E, 8.2/E.3, 8.2/G, 9/A.2, 9/C, 9/E, 9/E.3, 9/G, 9/H, 10/A.2, 10/B, ELEVATOR PIT AND PIER AT 9/D

-GRADE BEAMS: 6 FROM A.2 TO B, B FROM 6 TO 7, 7 FROM A.2 TO B, A.2 FROM

7 TO 9,

LINE 6 FROM H.6 TO. H, LINE A.2 FROM 9 TO 10, LINE 10 FROM A.2 TO B

\*\*AREA "C" \*\*

-COLUMN PADS: 10/H.6, 10/H

-GRADE BEAMS: LINE H6.3 AREA B CLOCKWISE TO H10.4

## **Comments:**