



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20204551, Public Works Right of Way Permit

Address: 224 SE FLORENCE AVE, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Passed	Friday, December 18, 2020

Corrective Action Required

1	Misc	Site visit on 12/17/20
		GF drop had been installed.

Comments: