

SOIL SAMPLE PICK-UP REPORT

Report Number: 02191565.0001
Service Date: 01/09/20
Report Date: 01/14/20
Task: 02 - Laboratory Soil/Aggregate Testing

Terracon

15620 W 113th St
Lenexa, KS 66219-5102
913-492-7777

Client

Axiom Northwest Construction, Inc.
Attn: Norm Hellings
2232 Broadway
Suite 101
Everett, WA 98201

Project

DCI - Lee's Summit
2001 Shamrock Rd
Lee's Summit, MO

Project Number: 02191565

SUMMARY:

As requested, a Terracon representative retrieved a sample from the location referenced below. The sample was returned to our laboratory for the requested scope of testing. Results of our laboratory testing will be submitted under separate cover. The sampled material will be discarded upon completion of our requested scope of testing.

Sample A:

Visual Classification*: Fat clay, brown and grayish brown.

Material Source: Off-site borrow

Sample Location: Stockpile from off-site borrow at 1905 Shamrock Ave.

Proposed Use: Engineered fill

Requested Testing: Standard Proctor & Atterberg Limits

Source of Specifications: Project Specifications

*Based on visual and tactile classification only

Services:

Terracon Rep.: Caleb Brewer


Reported To: Norm with Axiom

Contractor: Axiom Northwest Construction

Report Distribution:

(1) Axiom Northwest Construction, Inc.,
norm@axiomnw.com

Reviewed By:


Feras El Ghoussein
Project Manager

The tests were performed in general accordance with applicable ASTM, AASHTO, or DOT test methods. This report is exclusively for the use of the client indicated above and shall not be reproduced except in full without the written consent of our company. Test results transmitted herein are only applicable to the actual samples tested at the location(s) referenced and are not necessarily indicative of the properties of other apparently similar or identical materials.

SOIL SAMPLE PICK-UP REPORT

Report Number: 02191565.0002
Service Date: 02/27/20
Report Date: 03/11/20
Task: 01 - Earthwork Observation and Testing



15620 W 113th St
Lenexa, KS 66219-5102
913-492-7777

Client

Axiom Northwest Construction, Inc.
Attn: Norm Hellings
2232 Broadway
Suite 101
Everett, WA 98201

Project

DCI - Lee's Summit
2001 Shamrock Rd
Lee's Summit, MO

Project Number: 02191565

SUMMARY:

As requested, a Terracon representative retrieved 2 samples from the locations referenced below. The samples were returned to our laboratory for the requested scope of testing. Results of our laboratory testing will be submitted under separate cover. The sampled material will be discarded upon completion of our requested scope of testing.

Sample A:

Visual Classification*: Weathered shale with trace gravel, gray
Material Source: Off-site borrow
Sample Location: 95th and Loiret, Lenexa, KS
Proposed Use: Structural Fill
Requested Testing: Standard Proctor
*Based on visual and tactile classification only.


SAMPLE B:

Visual Classification*: Weathered shale with trace gravel, yellowish brown
Material Source: Off-site borrow
Sample Location: 81st and Flint, Lenexa, KS
Proposed Use: Structural Fill
Requested Testing: Standard Proctor
*Based on visual and tactile classification only.

Services:

Terracon Rep.: Kevin Hollis
Reported To: Norm with Axiom
Contractor: Axiom Northwest Construction
Report Distribution:
(1) Axiom Northwest Construction, Inc.,
norm@axiomnw.com

Reviewed By:


Feras El Ghoussein
Project Manager

The tests were performed in general accordance with applicable ASTM, AASHTO, or DOT test methods. This report is exclusively for the use of the client indicated above and shall not be reproduced except in full without the written consent of our company. Test results transmitted herein are only applicable to the actual samples tested at the location(s) referenced and are not necessarily indicative of the properties of other apparently similar or identical materials.

SOIL SAMPLE PICK-UP REPORT

Report Number: 02191565.0025
Service Date: 05/04/20
Report Date: 05/10/20
Task: 01 - Earthwork Observation and Testing

Terracon

15620 W 113th St
Lenexa, KS 66219-5102
913-492-7777

Client

Axiom Northwest Construction, Inc.
Attn: Norm Hellings
2232 Broadway
Suite 101
Everett, WA 98201

Project

DCI - Lee's Summit
2001 Shamrock Rd
Lee's Summit, MO

Project Number: 02191565

SUMMARY:

As requested, a Terracon representative retrieved a sample from the location referenced below. The sample was returned to our laboratory for the requested scope of testing. Results of our laboratory testing will be submitted under separate cover. The sampled material will be discarded upon completion of our requested scope of testing.

Sample A:


Visual Classification*: Limestone screenings
Material Source: Quarry
Proposed Use: LVC fill
Requested Testing: Standard Proctor

Services:

Terracon Rep.: Kevin L. McCurdy
Reported To: N/A
Contractor: Axiom Northwest Construction
Report Distribution:

(1) Axiom Northwest Construction, Inc.,
norm@axiomnw.com

Reviewed By:


Feras El Ghoussein
Project Manager

The tests were performed in general accordance with applicable ASTM, AASHTO, or DOT test methods. This report is exclusively for the use of the client indicated above and shall not be reproduced except in full without the written consent of our company. Test results transmitted herein are only applicable to the actual samples tested at the location(s) referenced and are not necessarily indicative of the properties of other apparently similar or identical materials.