

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20202176
Address: 1520 SW SUGAR TREE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	John Morris	Failed	Wednesday, December 23, 2020

Corrective Action Required:

1	Misc	-Holes for pex bored less than 2" together in floor joist, 1st floor above living room -Bocca protection plate at DWV vent 2nd floor bath #2 top plate -Nail dbl truss girders together per plans -bed#4
---	------	--

Comments: