CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20192096 Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: All Rough Inspection - Commercial		Inspector:	Outcome:	Date:
		Michael Harkins	Partial	Tuesday, December 29, 2020
	Action Required:			
1	FOURTH FLOOR	420A,435,436,437,438, -460- 426;444,447,448, Corridor 419 to room 4 -CORRIDOR 419,422,42 -AREA "D"- -CORRIDOR 412,-	CORRIDOR 412,-	
		-432,433,434,- - 417 COMMUNITY RO(OM ABOVE CEILING &	WALLS -
				1,412, 421,422,423,424,425,426,427,428
		-AREA "B"- - CORRIDOR 409 JOIST - CORRIDOR 405 JOIST - CORRIDOR 403 JOIST	HANGERS -	

	Action Required: THIRD FLOOR	: CORRECTIONS BELOW : :- CORRIDOR 411 ADD BLOCKING & NAIL J HANGER -: Section "E" 345-344-343- 342-361-362-363-341-364-340-322-326-327, 329, -corridor framing ceiling -320A,321A, 324A, 325A, 337, 338, 339, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360,365, 366, 367, -
	e Action Required: SECOND FLOOR	Corridor 319 to room 364 ok Corridor 322, 326, 327, 329,
		SECTION "D" CORRIDOR FRAMING CEILING 312, - AREA "B" - CORRIDOR 311, JOIST HANGERS - - CORRIDOR 309, JOIST HANGERS - - CORRIODR 305, JOIST HANGERS - - CORRIDOR 301, JOIST HANGERS -
		-301,302,303,304,305,306,307,309,310,312,313,314,315,316,317,318,319,320,3 21,322,323,324,325,326,327,328,329,330,331,332,333,334,335,336,-
Corrective		310A rough approved
		'Section "E" Ok- 220A,224A,237,238,239,240,241,242,243,244,245, 246, 261,262. 225A, 226, 264,265,266,267 - -,247,249,250,251,252, 253,254,256,257,258,259,260,
		-248- SEAL DEAD SPACE AT FUTURE SHAFT
		Corridor 219 to room 240 ok Corridor 222 to stairs ok - CORRIDOR 222 FROM STAIRS TO END OF CORRIDOR 226 - SECTION "E" - CORRIDOR 229 ALL ROUGH -
		SECTION "D" CORRIDOR CEILING FRAMING 212, -SECTION "B" - -CORRIDOR 209 JOIST HANGERS - - CORRIDOR 205, JOIST HANGERS - - CORRIDOR 203, JOIST HANGERS - - CORRIDOR 201 JOIST HANGERS - - CORRIDOR 211 JOIST HANGERS - - 201,202,203,204,205,206,207,208,209,210,211,212, 213,214,215,216,217,218,219,220,221,222,223,224, 225,226,227,228,229,230,231,232,233,234,235,236 -

- 210A SEAL PENETRATIONS AT LINE SET & LOW VOLT -

Corrective Action Required: 4 FIRST FLOOR

BUILDING "B"

-CORRIDOR 103 LINE 4.3 TO 2 ** METAL FRAMING ONLY

BUILDING "C" AREAS OK;

-LOBBY EXTERIOR EAST WALL **METAL FRAMING ONLY -

- 2ND TIER LOBBY NORTH & SOUTH WALLS AT RESTROOMS -
- NORTH RETAIL ALL ROUGH ---
- RETAIL E WEST WALL -
- LOWER LOBBY NORTH & SOUTH ENDS 2HR DEMISING WALL -

- UPPER & LOWER LOBBY ALL ROUGH -

Section "E" OK-120A,121,122,123,124,125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138,

Corridor 119 to room 125 ok Corridor 122,129 ok CORRIDOR CEILING 112, 129, -Corridor 126 Metal Stud Framing from north exit to line 8.6

-CORRIDOR 124- PROVIDE HANGERS/ CONNECTIONS ON FLOOR JOISTS BOTH ENDS-

-ROOM 132-

-SEAL HOLE IN CORRIDOR WALL AT CLEAN OUT

- SECTION "B" -
- CORRIDOR 109, JOIST HANGERS -
- CORRIDOR 105, JOIST HANGERS -
- CORRIDOR 111, CEILING JOIST HANGERS :

101,102,103,104,105,106,107,108,109,110,110A,111,112,113,114,115,116,117,1 18,119,120, -

- 134,135 YOGA,FITNESS ROOM ABOVE CEILING ROUGH ONLY -

- 138,139, MECH ROOM WEST OF RESTROOMS ABOVE CEILING FOR FIRE LID -

Informational:

5 STAIR TOWER 3

Corrective Action Required:

- STAIR TOWER 123 "C" NORTH AREAS INSPECTED: - STAIR TOWER "C" -
- ALL ROUGH APPROVED -

6	STAIR TOWER 2	STAIR TOWER 113 "B" WEST CENTER AREAS INSPECTED:
		- ROUGH - IN APPROVED FLOORS 1 THRU 4 -

Comments: