

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20210035, Public Works Right of Way Permit
Address: 132 NW MACKENZIE DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Passed	Tuesday, January 12, 2021

Corrective Action Required

1 Misc

Site visit: The work has been completed and the area backfilled. This is an active home build site. Vegetation was not established prior to Rylie Equipments repair work.

Comments: