



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20204278, Public Works Right of Way Permit
Address: 2926 SW ARBOR TREE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Passed	Wednesday, January 13, 2021

Corrective Action Required

1 Misc

Site visit: Spire has installed the service to the home. This is an active home build site, vegetation has not been established.

Comments: