## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRSUBD20201877 Address:

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Water Line - Construction Inspection		Inspector: John Jackson	Outcome: Partial	Date: Wednesday, January 13, 2021
1	Misc	Contractor put toget complete(Project sit hydrants and fittings piping to be delivere South side of I-470 H	her 12" Certa-Lok for the e North side of I-470). Th that were installed. Cor d to continue installatio wy	ne South side to the North side. installation after the boring is must blocks were poured on itractor is waiting for more n of piping head North on the
Inform	ational:	This on the wrong pr	oject! It should be on Pa	ragon Star.
2 Inform	Misc national:	10/19/20 Monday Str	eet crossing for Lines 1 &	2 have be installed.
14	Misc	line #1 just East of th	_	ds on 8" water main Sta. 5+30 ne #1 to Sta. 7+83.79 Line #2). nd Lines #1 & 2.
Inform	ational:			
13	Misc	Line #1 & 60' on Line plan. Contractor (Cha	#2. Contractor also will p ad of Holthouse the own	60' of 12" PVC water pipe on oour Three straddle block as per er) was informed that he needs ed changes to Water Line #1. I

		will not perform inspection that allow the contractor to Tie-in to existing water main until the updates to the as-built of Water Line #1.		
Informati	ional·			
12	Misc	1/11/21 Monday 4:20 PM		
12	IVIISC	Contractor didn't notify me that they would be on site. (So my inspection will		
		run late all overtime for this day will be charge to this project.)		
		Approximately 30' of 12 PVC on line #1 Sta. 12+17 was installed just short of		
		the tie-in point to existing water main. Contractor installed mega lugs for		
		straddle block as-per project plans. Contractor was informed they needs to		
	· · · · · · ·	clean street of track mud in the street.		
Informational:				
11	Misc	12/30/20 Wednesday 11:10AM		
		On 12/28/20 contractor installed approximately 150' of 12" PVC line #2 which		
		end with the installation of Fire Hydrant @12+93.19. Contractor poured thrust		
		blocks bends on lines #1 & #2 .		
Informati				
10	Misc	12/23/20 Wednesday 9:12AM		
		Contractor (Holthouse Talked with Chad) about the unapproved field		
		changes that were made.		
		Chad talked with the Engineer Solutions and they well due the field survey.		
		The inspector has observed no structural problem with redesign, but wants		
		the contractor to submit changes so they can be properly recorded and		
		approved. I will inform the City review Engineer of the field changes that		
		were made to fittings and elevation throughout Line #1.		
Partial Co	prrection:			
9	Misc	Contractor (Holthouse/Brain's crew) contractor replaced 22 1/2 bends with 11		
		1/4 bends and move the location 10' West of Storm Line @ 8+40 and the		
		second 12' to the East 8+40 on LIne #1.		
		Also the 45 degree bends where not used but the 18" of clearance was		
		achieved. Contractor did not consult the inspector when on waterline were		
		made the changes to the depth of pipe.		
Informati	ional:			
8	Misc	Contractor (Holthouse/Brain's crew) installed approximately 320' of 12" PVC		
		water main on Line #1 and four 11 1/4 bends (as-per plans).		
Informational:				
7	Misc	12/18/20 Friday		
		Contractor installed approximately 350 of 12" PVC of water main on Line #2		
		Stopping @ the		
		Sta 0+41 A 45 deg bend. Starting from the Cross 12"x12" on Line #1 6+28.96 12"		
		PVC (Sta 7+83.79 Line #2). Approximately 170' of 12" PVC was installed on		
		Line #1.		
Informational:				
6	Misc	12/17/20 Thursday 3:20PM		
		Contractor installed approximately 150' more feet of 12" PVC water main on		
		line #2.		
		Contractor stopped around Sta 3+50 for the evening. Contractor backfilled		
		Contractor stopped around Sta 3+50 for the evening. Contractor backfilled		
Informati	ional:	Contractor stopped around Sta 3+50 for the evening. Contractor backfilled excavation of installed water pipe and fenced off the 12"X12" Cross @ NE		
Informati 5	ional: Misc	Contractor stopped around Sta 3+50 for the evening. Contractor backfilled excavation of installed water pipe and fenced off the 12"X12" Cross @ NE		

		Contractor installed approximately 275' of 12" PVC water main on Line # 2 from Sta 7+83.79 12"X12" cross to approximately Sta 5+03.
Inform	ational:	
4	Misc	12/17/20 Thursday 8:15AM
		Contractor began installed 12"x12" Crossing for Lines #1 & 2.
Inform	ational:	
3	Misc	12/16/20 Wednesday
		Contractor (Brain of Holthouse Construction) excavated water line crossing at line #1 to began water line installation of project. Material Verification once
		material arrive on site.

## **Comments:**