

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20201531
Address: 4399 SW AMETHYST DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Miscellaneous Inspection	John DiMauro	Failed	Thursday, January 21, 2021

Informational:
1 Misc JOHN DIMAURO 1/21/2021

THE SS MANHOLE AT THE REAR OF THE PROPERTY (SOUTHEAST CORNER) APPEARS TO BE SET TO HIGH. THE MH IS APPROXIMATELY 4' FT FROM THE SIDEWALK AND APPROXIMATELY 20" IN HIGHER THAN THE SIDEWALK. THE SIDEWALK APPEARS TO BE SET AT THE CORRECT ELEVATION.

Comments: