

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20192096  
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Above Ceiling Inspection</b>	Michael Harkins	Partial	Tuesday, January 26, 2021

Corrective Action Required:	
1 SECOND FLOOR	- SECTION E PHASE 1 JOIST HANGERS CORRIDOR & DECKS -  CORRIDOR 219 ABOVE GRID CORRIDOR 222 ABOVE GRID CORRIDOR 226 ABOVE GRID CORRIDOR 229 ABOVE GRID

Corrective Action Required:	
2 THIRD FLOOR	- SECTION E PHASE 1 JOIST HANGER CORRIDOR & DECKS - - CORRIDOR 319 ABOVE CEILING GRID- - CORRIDOR 322 ABOVE CEILING GRID- - CORRIDOR 326 ABOVE CEILING GRID- - CORRIDOR 329 ABOVE CEILING GRID- - AREA "D" - CORRIDOR 312 ABOVE CEILING GRID -

Corrective Action Required:	
3 FOURTH FLOOR	- SECTION E PHASE 1 JOIST HANGERS CORRIDOR -  ABOVE CEILING GRID CORRIDORS CORRIDOR 419,422,423,426,429  - 417 AMENITY DECK ROOM ABOVE CEILING OK TO COVER -

Corrective Action Required:  
4 FIRST FLOOR

- 415A,416A, AMENITY DECK RESTROOMS HARD LIDS -
- AREA D CORRIDOR 412 ABOVE GRID FOR HARD LID -
- LOWER LEVEL LOBBY SOUTH MECH ROOM ABOVE CEILING OK TO COVER -
- CORRIDOR 119 ABOVE CEILING GRID -
- CORRIDOR 122 ABOVE CEILING GRID -
- CORRIDOR 129 ABOVE CEILING GRID -
- 134 & 135 YOGA/FITNESS ROOMS HARD LID -
- 138A, 139A FITNESS RESTROOM ABOVE HARD LID -

**Comments:**