

Inspection Summary

Permit #: PRCOM20191955, Building Permit - Commercial
ATTIC STORAGE OF LEES SUMMIT
Address: 920 NE DEERBROOK ST, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Water Utilities	Curtis Deason	Failed	Tuesday, February 02, 2021
Occupancy Inspection - Planning	Jennifer Thompson	Temporary C of O	Tuesday, February 02, 2021
Occupancy Inspection - Engineering	John Jackson	Temporary C of O	Tuesday, February 02, 2021

Informational

1 We are good with TCO.

1. Clean up the frozen mud that is in the parking lot on the south side of the building.
2. 70% vegetation needs to be established throughout the entire site.
3. Trash and debris need to be cleaned up on the site.

Informational

2

1. Establish 70% vegetation on all disturbed area's.
2. Clean up all trash and debris from site.

Please complete by March 15, 2021

Occupancy Inspection - Water Utilities	Curtis Deason	Failed	Tuesday, February 02, 2021
--	---------------	--------	----------------------------

Comments:
