

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Permit #:PRPWRW20210222, Public Works Right of Way Permit Address: 1125 NE DOUGLAS ST, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Site Visit Inspection Bob Burns Partial Thursday, February 25, 2021

Corrective Action Required

1 Misc The crew was placing the electrical cabinet today. The lane shift

sign heading northbound was backwards again. I spoke with the Forman onsite and stressed the importance of getting the

signage correct.

Site Visit Inspection Matt Munger Partial Thursday, February 25, 2021

Corrective Action Required

1 Misc Site visit: At 1:30 pm today the crews were onsite, I drove both

north and south on Douglas through the traffic control. There was advanced warning signs in place and cones setup to close

off the lanes of traffic on both sides of Douglas.

**Comments:**