CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street

Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192096

Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Above Ceiling Inspection Michael Harkins Partial Friday, February 26,

2021

Corrective Action Required:

1 SECOND FLOOR - SECTION E PHASE 1 JOIST HANGERS CORRIDOR & DECKS -

CORRIDOR 219 ABOVE GRID CORRIDOR 222 ABOVE GRID CORRIDOR 226 ABOVE GRID CORRIDOR 229 ABOVE GRID

AREA D

CORRIDOR 212 ABOVE GRID CORRIDOR 227 ABOVE GRID

Corrective Action Required:

2 THIRD FLOOR - SECTION E PHASE 1 JOIST HANGER CORRIDOR & DECKS -

CORRIDOR 319 ABOVE CEILING GRID CORRIDOR 322 ABOVE CEILING GRID CORRIDOR 326 ABOVE CEILING GRID CORRIODR 329 ABOVE CEILING GRID-

- AREA "D"

- CORRIDOR 312 ABOVE CEILING GRID - CORRIDOR 327 ABOVE CEILING GRID -

- AREA "B" -

- CORRIDOR 303 ABOVE CEILING GRID - CORRIDOR 305 ABOVE CEILING GRID-

- CORRIDOR 311 ABOVE CEILING GRID -
- CORRIDOR 309 ABOVE CEILING GRID -
- CORRIDOR 309 EXPANSION JOINT WALLS & CEILING -

Corrective Action Required:

3 FOURTH FLOOR

- SECTION E PHASE 1 JOIST HANGERS CORRIDOR -

ABOVE CEILING GRID CORRIDORS CORRIDOR 419,422,423,426,429

- 417 AMENITY DECK ROOM ABOVE CEILING OK TO COVER -
- 415A,416A, AMENITY DECK RESTROOMS HARD LIDS -
- AREA D CORRIDOR 412 ABOVE GRID FOR HARD LID -
- CORRIODR 427 ABOVE GRID -
- AREA "B"
- CORRIDOR 403 ABOVE GRID -
- CORRIODR 405 ABOVE GRID -
- CORRIODR 409 ABOVE GRID -
- CORRIDOR 411 ABOVE GRID -
- CORRIDOR 411 EXPANSION JOINT WALLS & ABOVE CEILING -

Corrective Action Required:

4 FIRST FLOOR

- LOWER LEVEL LOBBY SOUTH MECH ROOM ABOVE CEILING OK TO COVER -
- CORRIDOR 119 ABOVE CEILING GRID -
- CORRIDOR 122 ABOVE CEILING GRID -
- CORRIDOR 129 ABOVE CEILING GRID -
- 134 & 135 YOGA/FITNESS ROOMS HARD LID -
- 138A, 139A FITNESS RESTROOM ABOVE HARD LID -

Corrective Action Required:

5 ELEVATOR 2

- ELEVATOR "B" LOBBY FLOORS 1,2,3,4, -

Corrective Action Required:

6 ELEVATOR 3

ELEVATOR "C"

- ABOVE CEILING LOBBY 1ST FLOOR -

Comments: