



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20210222, Public Works Right of Way Permit  
Address: 1125 NE DOUGLAS ST, LEES SUMMIT, MO 64086

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Bob Burns	Partial	Friday, February 26, 2021

Corrective Action Required	
1      Misc	Crews are working on installing the electrical cabinet. TTC is per plan and working well.

**Comments:**