CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20202637

Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Footing Inspection - John Morris Partial Monday, March 01,

Commercial

Informational:

1 THE FOLLOWING **AREA "A"**

AREAS ARE -COMPLETE
APPROVED **AREA "B"*

-COMPLETE-**AREA "C" ** -COMPLETE-

AREA "D"

-COLUMN PADS: 15/M, 15/N, 15/C, 15/D, 15/E, 15/E.3, 15/F, 15/G, 15/H.7,15/V, 15/W, 18/P.1, 18/Q, 18/R.5, 16/W, 17/W, 16/G, 17/H.6,

2021

17/V, 18/U.2, 18/V, 17.1/W, 16/H.6, 16/V, 15.5/H.6,

-GRADE BEAMS: LINE 15 FROM M TO W, LINE 19.1 FROM T.4 TO 0.9, LINE P FROM 18-19.1, LINE 18 FROM P.1 TO S, LINE R.5 FROM 18 TO 19.1, LINE W

FROM 15 TO 18, LINE 18 FROM W TO X, LINE X FROM 18 TO 19.1

-STEM WALL LINE 15 TO W AND W FROM 15 TO 17

-STEM WALL LINE 19.1

**AREA "E" **

-GRADE BEAM: LINE 19.1 FROM T.4 TO 0.9, LINE 20.8 FROM P.1 TO U.2, LINE 0.9 FROM 19.1 TO 20' NORTH OF 20.8, LINE 21 FROM 0.9 TO V, LINE Q FROM 21 TO

15' SOUTH, LINE V FROM 21 TO 15' SOUTH, LINE E.19 FROM 18 TO 19.5, LINE 19,5 FROM E.18 TO E.19, LINE E.18 FROM 19.5 TO 20.1

-COLUMN PADS C12.2,D12.2, D13 15' SOUTH, E12.2, E12.2,E13,E3,12.2,C13, E.9/18, E.9/19.1, E.9/19.5, E.18/19.5, E.18/20.1

AREA G

-GRADE BEAM: LINE X FROM 18 TO 20.5, LINE 20 FROM X TO V, LINE 21 FROM U.8 TO W, LINE W FROM 21 TO 23, STEM WALL LINE X FROM 18 TO 20 -MECHANICAL PAD 1 and 2 BETWEEN LINE 20 AND 21 U.4 - 22 through 25 & 23 line- U.2 through W

AREA F

23.8 line - u.5 through Q line Q line - 24 through 22 Stair line between Q & R - 25 through 23.8

Comments: