CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20202637 Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Footing Inspection - Commercial		Inspector:	Outcome:	Date:
		John Morris	Partial	Tuesday, March 02, 2021
Informat	ional:			
1	THE FOLLOWING AREAS ARE APPROVED	15/H.7,15/V, 15/W, 1 17/V, 18/U.2, 18/V, 1 -GRADE BEAMS: LINI FROM 18-19.1, LINE 1 FROM 15 TO 18, LINE	7.1/W, 16/H.6, 16/V, 15.9 E 15 FROM M TO W, LINE 18 FROM P.1 TO S, LINE R 18 FROM W TO X, LINE X TO W AND W FROM 15 T	N, 17/ W, 16/G, 17/G, 17/H.6, 5/H.6, 19.1 FROM T.4 TO 0.9, LINE P .5 FROM 18 TO 19.1, LINE W FROM 18 TO 19.1
	**AREA "E" ** -GRADE BEAM: LINE 19.1 FR		19.1 FROM T.4 TO 0.9, LII	NE 20.8 FROM P.1 TO U.2, LINE 0.9 DM 0.9 TO V, LINE Q FROM 21 TO

15' SOUTH, LINE V FROM 21 TO 15' SOUTH, LINE E.19 FROM 18 TO 19.5, LINE 19,5 FROM E.18 TO E.19, LINE E.18 FROM 19.5 TO 20.1

-COLUMN PADS C12.2,D12.2, D13 15' SOUTH, E12.2, E12.2,E13,E3,12.2,C13, E.9/18, E.9/19.1, E.9/19.5, E.18/19.5, E.18/20.1

AREA G -GRADE BEAM: LINE X FROM 18 TO 20.5, LINE 20 FROM X TO V, LINE 21 FROM U.8 TO W, LINE W FROM 21 TO 23, STEM WALL LINE X FROM 18 TO 20 -MECHANICAL PAD 1 and 2 BETWEEN LINE 20 AND 21 U.4 - 22 to 25 & 23 line- U.2 to W X line- 20 to 21 21 line - V.8 to X.2

AREA F 23.8 line - u.5 to Q line Q line - 24 to 22 Stair line between Q & R - 25 to 23.8

Comments: