



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20210222, Public Works Right of Way Permit  
Address: 1125 NE DOUGLAS ST, LEES SUMMIT, MO 64086

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Bob Burns	Partial	Wednesday, March 03, 2021

**Corrective Action Required**

1	Misc	The new pole has been installed. Crews are onsite working on wiring the pole. TTC is good.
---	------	--

**Comments:**