## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20202637 Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Footing Inspection - Commercial		Patrick Schonfeldt	Partial	Thursday, March 04, 2021
Informati	onal:			
1	THE FOLLOWING AREAS ARE APPROVED	15/H.7,15/V, 15/W, 18/P 17/V, 18/U.2, 18/V, 17.1/ -GRADE BEAMS: LINE 15 FROM 18-19.1, LINE 18 FF FROM 15 TO 18, LINE 18 FF	15/N, 15/C, 15/D, 15/E, 15/E .1, 18/Q, 18/R.5, 16/W, 17/ ′W, 16/H.6, 16/V, 15.5/H.6, FROM M TO W, LINE 19.1 FI ROM P.1 TO S, LINE R.5 FRO FROM W TO X, LINE X FROM W AND W FROM 15 TO17	W, 16/G, 17/G, 17/H.6, ROM T.4 TO 0.9, LINE P M 18 TO 19.1, LINE W
			L FROM T.4 TO 0.9, LINE 20.8 H OF 20.8, LINE 21 FROM 0.9	

15' SOUTH, LINE V FROM 21 TO 15' SOUTH, LINE E.19 FROM 18 TO 19.5, LINE 19,5 FROM E.18 TO E.19, LINE E.18 FROM 19.5 TO 20.1

-COLUMN PADS C12.2,D12.2, D13 15' SOUTH, E12.2, E12.2,E13,E3,12.2,C13, E.9/18, E.9/19.1, E.9/19.5, E.18/19.5, E.18/20.1

\*\*AREA G\*\* -GRADE BEAM: LINE X FROM 18 TO 20.5, LINE 20 FROM X TO V, LINE 21 FROM U.8 TO W, LINE W FROM 21 TO 23, STEM WALL LINE X FROM 18 TO 20 -MECHANICAL PAD 1 and 2 BETWEEN LINE 20 AND 21 U.4 - 22 to 25 & 23 line- U.2 to W X line- 20 to 21 21 line - V.8 to X.2

\*\*AREA F\*\* 23.8 line - u.5 to Q line Q line - 24 to 22 Stair line between Q & R - 25 to 23.8

3/4/21-(2) PADS GRIDS 20 LINE- 21, V TO X 23 LINE TO 24, X.2 LINE TO U.5 23.8 LINE TO 25, Q2 LINE , 0.1 LINE TO 24 21 LINE TO 23.8, P

Comments: