# CITY OF LEE'S SUMMIT **Development Services Department** 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

# **Inspection Summary**

Permit #: PRCOM20192096

Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection -

Commercial

Michael Harkins

Partial

Friday, March 05, 2021

#### Corrective Action Required:

**FOURTH FLOOR** 1

AREA"E"- UNITS-

420A,435,436,437,438,439,440,461,441,442,459-443-459-461-462-463-464-4

65-460-426;444,447,448,449,450,451,457,424A, 425A

Corridor 419 to room 439 ok

-CORRIDOR 419,422,426, 427, 429, CEILINGS & WALLS -

- -AREA "D"-
- -CORRIDOR 412.-
- -432,433,434,-
- 417 COMMUNITY ROOM ABOVE CEILING & WALLS -

401,402,403,404,404A,405,406,406A,407,408,408A, 409,410,410A,411,412,413,414,415,415A,416,416A, 417,418,419,420,421,422,423,424,425,426,427,428, 429, 430, 431, -

- -AREA "B"-
- CORRIDOR 409 JOIST HANGERS -
- CORRIDOR 405 JOIST HANGERS -
- CORRIDOR 403 JOIST HANGERS -

#### Corrective Action Required:

### 2 THIRD FLOOR

Section "E"

345-344-343- 342-361-362-363-341-364-340-322-326-327, 329, -corridor framing ceiling

-320A,321A, 324A, 325A, 337, 338, 339, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360,365, 366, 367, -

Corridor 319 to room 364 ok Corridor 322, 326, 327, 329,

#### SECTION "D"

**CORRIDOR FRAMING CEILING 312,** 

- AREA "B"
- CORRIDOR 311, JOIST HANGERS -
- CORRIDOR 309, JOIST HANGERS -
- CORRIODR 305, JOIST HANGERS -
- CORRIDOR 301, JOIST HANGERS -

-301,302,303,304,304A,305,306,306A,307,308A,309, 310,310A,312,313,314,315,316,317,318,319,320,321,322,323,324,325,326,32 7,328,329,330,331,332,333, 334,335,336,-

#### Corrective Action Required:

3 SECOND FLOOR

'Section "E" Ok- 220A,224A,237,238,239,240,241,242,243,244,245, 246, 261,262. 225A, 226, 264,265,266,267 - -,247,249,250,251,252, 253,254,256,257,258,259,260,

-248- SEAL DEAD SPACE AT FUTURE SHAFT

Corridor 219 to room 240 ok Corridor 222 to stairs ok

- CORRIDOR 222 FROM STAIRS TO END OF CORRIDOR 226 -

SECTION "E"

- CORRIDOR 229 ALL ROUGH -

SECTION "D"

CORRIDOR CEILING FRAMING 212,

- -SECTION "B" -
- -CORRIDOR 209 JOIST HANGERS -
- CORRIDOR 205, JOIST HANGERS -
- CORRIDOR 203, JOIST HANGERS -
- CORRIDOR 201 JOIST HANGERS -
- CORRIDOR 211 JOIST HANGERS -
- 201,202,203,204,204A,205,206,206B,207,208,208A,

209,210,210A,211,212,213,214,215,216,217,218,219,220,221,222,223,224,22

5,226,227,228,229,230,231,

232,233, 234,235,236 -

#### Corrective Action Required:

4 FIRST FLOOR

**BUILDING "B"** 

-CORRIDOR 103 LINE 4.3 TO 2 \*\* METAL FRAMING ONLY

BUILDING "C" AREAS OK;

- -LOBBY EXTERIOR EAST WALL \*\*METAL FRAMING ONLY -
- 2ND TIER LOBBY NORTH & SOUTH WALLS AT RESTROOMS -
- NORTH RETAIL ALL ROUGH ---
- RETAIL E WEST WALL -
- LOWER LOBBY NORTH & SOUTH ENDS 2HR DEMISING WALL -
- UPPER & LOWER LOBBY ALL ROUGH -

Section "E" OK-120A,121,122,123,124,125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138,

Corridor 119 to room 125 ok

Corridor 122,129 ok

CORRIDOR CEILING 112, 129,

- -Corridor 126 Metal Stud Framing from north exit to line 8.6
- -CORRIDOR 124- PROVIDE HANGERS/ CONNECTIONS ON FLOOR JOISTS BOTH ENDS-
- -ROOM 132-
  - -SEAL HOLE IN CORRIDOR WALL AT CLEAN OUT
- SECTION "B" -
- CORRIDOR 109, JOIST HANGERS -
- CORRIDOR 105, JOIST HANGERS -
- CORRIDOR 111, CEILING JOIST HANGERS:

101,102,103,104,105,106,107,108,108A,109,110,110A,111,112,113,114,115,1 16,117,118,119,120, -

- 134,135 YOGA,FITNESS ROOM ALL ROUGH -
- 138,139, MECH ROOM WEST OF RESTROOMS ABOVE CEILING FOR FIRE LID, ALL ROUGH -
- SOUTH RETAIL WALL ROUGH-
- 131,143, STORAGE ROOMS -
- 142 MECH ROOM -
- 141 TRASH ROOM MISSING NORTH WALL -

#### Informational:

5 STAIR TOWER 3

STAIR TOWER 123 "C" NORTH AREAS INSPECTED:

- STAIR TOWER "C" -
- ALL ROUGH APPROVED -

#### Corrective Action Required:

6 STAIR TOWER 2

STAIR TOWER 113 "B" WEST CENTER AREAS INSPECTED:

- ROUGH - IN APPROVED FLOORS 1 THRU 4 -

Corrective Action Required:

7 STAIR TOWER 1 - STAIR TOWER "A" -

- ALL ROUGH STAIR "A" FLOORS 1 THRU 4 APPROVED -

Corrective Action Required:

8 LOWER LEVEL - 020,021,022,024, GARAGE BIKE STORAGE & STORAGE ROOMS -

- ELEVATOR A & C VESTIBULES AT GARAGE LEVEL -

### **Comments:**