



---

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

---

Permit #:PRPWRW20211010, Public Works Right of Way Permit

Address: 1626 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Partial	Thursday, March 11, 2021

Corrective Action Required

1	Misc	Site visit: No activity, locate flags are onsite.
---	------	---------------------------------------------------

**Comments:**