

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

---

Permit #:PRPWRW20210069, Public Works Right of Way Permit  
Address: 3904 SW PRYOR RD, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Passed	Thursday, March 11, 2021

Corrective Action Required  
1 Misc

This project was overseen through the Development Inspector John DiMauro. Closing this on our end.

**Comments:**