

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192096
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Above Ceiling Inspection	Michael Harkins	Partial	Tuesday, March 16, 2021

Corrective Action Required:
1 SECOND FLOOR - SECTION E PHASE 1 JOIST HANGERS CORRIDOR & DECKS -

CORRIDOR 219 ABOVE GRID
CORRIDOR 222 ABOVE GRID
CORRIDOR 226 ABOVE GRID
CORRIDOR 229 ABOVE GRID
AREA D
CORRIDOR 212 ABOVE GRID
CORRIDOR 227 ABOVE GRID
CORRIDOR 201 ABOVE GRID
CORRIDOR 203 ABOVE GRID
CORRIDOR 205 ABOVE GRID
CORRIDOR 209 ABOVE GRID
CORRIDOR 211 ABOVE GRID

Corrective Action Required:
2 THIRD FLOOR - SECTION E PHASE 1 JOIST HANGER CORRIDOR & DECKS -
- CORRIDOR 319 ABOVE CEILING GRID-
- CORRIDOR 322 ABOVE CEILING GRID-
- CORRIDOR 326 ABOVE CEILING GRID-
- CORRIDOR 329 ABOVE CEILING GRID-
- AREA "D"

- CORRIDOR 312 ABOVE CEILING GRID -
- CORRIDOR 327 ABOVE CEILING GRID -
- AREA "B" -
- CORRIDOR 303 ABOVE CEILING GRID
- CORRIDOR 305 ABOVE CEILING GRID-
- CORRIDOR 311 ABOVE CEILING GRID -
- CORRIDOR 309 ABOVE CEILING GRID -
- CORRIDOR 309 EXPANSION JOINT WALLS & CEILING -
- CORRIDOR 301 ABOVE CEILING GRID -

Corrective Action Required:

3 FOURTH FLOOR

- SECTION E PHASE 1 JOIST HANGERS CORRIDOR -

ABOVE CEILING GRID CORRIDORS

CORRIDOR 419,422,423,426,429

- 417 AMENITY DECK ROOM ABOVE CEILING OK TO COVER -
- 415A,416A, AMENITY DECK RESTROOMS HARD LIDS -
- AREA D CORRIDOR 412 ABOVE GRID FOR HARD LID -
- CORRIDOR 427 ABOVE GRID -
- AREA "B"
- CORRIDOR 403 ABOVE GRID -
- CORRIDOR 405 ABOVE GRID -
- CORRIDOR 409 ABOVE GRID -
- CORRIDOR 411 ABOVE GRID -
- CORRIDOR 411 EXPANSION JOINT WALLS & ABOVE CEILING -
- CORRIDOR 401 ABOVE GRID -

Corrective Action Required:

4 FIRST FLOOR

- LOWER LEVEL LOBBY SOUTH MECH ROOM ABOVE CEILING OK TO COVER -

- CORRIDOR 119 ABOVE CEILING GRID -
- CORRIDOR 122 ABOVE CEILING GRID -
- CORRIDOR 129 ABOVE CEILING GRID -

- 134 & 135 YOGA/FITNESS ROOMS HARD LID -
- 138A, 139A FITNESS RESTROOM ABOVE HARD LID -
- 135B FITNESS MECH ROOM ABOVE CEILING -
- CORRIDOR 105 ABOVE CEILING GRID -
- CORRIDOR 109 ABOVE CEILING GRID -
- CORRIDOR 111 ABOVE CEILING GRID TO STEEL COLUMN AT ELEVATOR -

Corrective Action Required:

5 ELEVATOR 2

- ELEVATOR "B" LOBBY FLOORS 1,2,3,4, -

Corrective Action Required:

6 ELEVATOR 3

ELEVATOR "C"

- ABOVE CEILING LOBBY 1ST FLOOR -

Corrective Action Required:

7 LOWER LEVEL

- ELEVATOR A & c VESTIBULES AT GARAGE LEVEL -

Comments: