

RESIDENTIAL ENGINEERING SERVICES

600 SW JEFFERSON ST, SUITE 300 LEE'S SUMMIT, MISSOURI 64063 (816) 399 -4901

Inspector				ction Date	Time	
Derek Perez			22 FEB '21		0815	
Address City		Permit #		Owner/Builder		
2041 NW Ashurst Dr Lee's Summit			PRRES20204957		Summit Homes	
			Subdivision			Lot #
Footing			Woodside Ridge		18	
Site Conditions (all must comply if applicable)			Slab (Basement or Garage As Marked)			
 Erosion control is in place and functional (inspection shall not be performed if erosion control is not functionally in compliance with the City requirements). Soils – bearing capacity as determined by: Bearing on undisturbed soil @ 2000 psf Per engineer report (comment or attach report) 				Formed & Reinforced Per City Approved Dwgs Garage structural slab per approved plan Basement slab on grade per approved plan 6 mil vapor barrier installed – not required for garage slab Isolation rings or block-outs are provided over pier pads for columns		
Cold weather protection			Footings			
 Foundation Wall Elements Wall forms centered on footings Wall thickness as specified on approved plans Reinforcement installed per approved plans Hold downs placed and installed properly Wall openings installed in accordance with City approved plans Deck/porch/balcony columns Top of wall and steps formed a minimum of 8" above proposed grading contours. Max. 12" block down at garage doors. Ufer Ground attachment rod left exposed (Give approx. location in comments) Retaining walls (for multiple walls on the plot plan 				 Reinforced per city approved plans or engineer report Deck/porch/balcony footings Footing – width, depth and location per approved plans and, or engineer report Solid jumps Frost depth (min. 36 inches) Column pads – basement Column/pad at garage structural slab 		
clarify which walls are being inspected in the comments)						

□ Installation per approved plans

Comments:

Concrete forms and installation of reinforcement are installed per approved plan specifications. Footings rest on AB3 mat per RES specifications. Footings are approved for concrete. Ufer rod is located in south east (rear left) corner of garage foundation wall.

This is to certify that I, or qualified individuals working under my direction, inspected and/ or tested the above checked items in accordance with the applicable City approved building and site plans, codes and engineering details. The work is complete and to the best of my knowledge was found to be in substantial compliance with the approved plans and specifications.

Signed:

BUH

Date:

22 FEB '21

