



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20211387, Public Works Right of Way Permit
Address: 4405 SW TANZANITE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Passed	Tuesday, March 30, 2021

Corrective Action Required

1	Misc	Site visit: It appears the line has been buried. There isn't sod or grass on this lot at this time.
---	------	---

Comments: