

Report Email:  
 Copy Email:  
 Lab Report Fax No:  
 Lab Report Contact 1:  
 Lab Report Contact 2:

Customer ID No: 9048  
 Customer PO No:  
 Collected By: Client  
 Invoice No: 49448

Redford Construction  
 17322 RT 291

Pleasant Hill, MO 64080

## Report of Analysis

Laboratory Report ID No:

**18546**

**Project Name:** Whispering Woods 2nd Plat

Item No.	Cat NO	ANALYSIS	COLLECTED	ANALYZED	REPORTING LIMIT	RESULTS
	Line NO	SAMPLE TYPE	SAMPLE SITE NOTES		TEST METHOD	
1	6191	<b>Bacteria, P/A E. Coli</b>	2/2/21	2/2/21	1	<b>Absent</b>
	118647	Grab	EOL - C		SM9223 B	
2	6191	<b>Bacteria, P/A E. Coli</b>	2/2/21	2/2/21	1	<b>Absent</b>
	118648	Grab	EOL - E		SM9223 B	
3	6190	<b>Bacteria, P/A T. Coliform</b>	2/2/21	2/2/21	1	<b>Absent</b>
	118646	Grab	EOL - C		SM9223 B	
4	6190	<b>Bacteria, P/A T. Coliform</b>	2/2/21	2/2/21	1	<b>Absent</b>
	118649	Grab	EOL - E		SM9223 B	

**Comments, if present, concern this Lab Work Order:**

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without written approval by Blue Valley Laboratories, Inc.