

Report Email:
 Copy Email:
 Lab Report Fax No:
 Lab Report Contact 1:
 Lab Report Contact 2:
 Customer ID No: 9048
 Customer PO No:
 Collected By: Client
 Invoice No:

Redford Construction
 17322 RT 291

Pleasant Hill, MO 64080

Report of Analysis

Laboratory Report ID No:

18541

Project Name: Whispering Woods 2nd Plat

Item No.	Cat NO	ANALYSIS	COLLECTED	ANALYZED	REPORTING LIMIT	RESULTS
	Line NO	SAMPLE TYPE	SAMPLE SITE NOTES		TEST METHOD	
1	6191	Bacteria, P/A E. Coli	2/1/21	2/1/21	1	Absent
	118589	Grab	EOL - C		SM9223 B	
2	6191	Bacteria, P/A E. Coli	2/1/21	2/1/21	1	Absent
	118590	Grab	EOL - E		SM9223 B	
3	6190	Bacteria, P/A T. Coliform	2/1/21	2/1/21	1	Absent
	118588	Grab	EOL - C		SM9223 B	
4	6190	Bacteria, P/A T. Coliform	2/1/21	2/1/21	1	Absent
	118591	Grab	EOL - E		SM9223 B	

Comments, if present, concern this Lab Work Order:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without written approval by Blue Valley Laboratories, Inc.