

Building Inspections Department  
Building Certification Form

Project Address: 3113 SW BLUE RIBBON STREET	Permit Number: 2021-0408
Subdivision: SUMMIT VIEW FARMS	Lot #: 53
Owner/Builder: SUMMIT VIEW FARMS DEVELOPMENT	Master Plan:

Indicate the type of inspection(s) being certified.

**STRUCTURAL ELEMENTS FOR FOUNDATION**

- ☒ Footing (Perimeter) Approved  
☐ Thickened Slab Footing Approved  
☐ Drilled Piers Approved  
☒ Concrete Encased Electrode Approved  
☐ Slab Insulation Approved  
  
☒ Pad(s) for Basement Steel Columns Approved  
☐ Pad(s) for Garage Steel Columns Approved  
  
☒ Pad(s) for Standard Structural Slab Approved  
☒ Pad(s) for Structural Slab (per Plan) Approved  
☒ Garage ☐ Basement

**Foundation Wall**

- ☐ Foundation Wall Approved  
Future Basement Slab shall be:  
☐ Slab-on-Grade ☐ Overdig Detail  
☐ Structural (per Plan)

- Future Garage Slab shall be:  
☐ Slab-on-Grade ☐ Overdig Detail  
☐ Std. Structural ☐ Structural (per Plan)

**Concrete Columns**

- ☐ Column(s) for Standard Structural Slab Approved  
☐ Garage  
☐ Column(s) for Structural Slab (per Plan) Approved  
☐ Garage ☐ Basement

**CONCRETE SLAB(S)**

- Slab on Grade** (Inspection not required)  
☐ Basement Slab on Grade Approved  
☐ Garage Slab on Grade Approved  
**Standard Overdig Slab Design**  
☐ Basement Overdig Slab Approved  
☐ Garage Overdig Slab Approved  
**Standard Structural Slab Design**  
☐ Garage Standard Structural Slab Approved  
**Structural Slab Design Per Approved Plan**  
☐ Basement Structural Slab Approved  
☐ Garage Structural Slab Approved

**PRE-BACKFILL**

- ☐ Foundation Drain Approved  
☐ Mechanical ☐ Daylight  
☐ Dampproofing Approved

**SOILS (Include Test Results)**

- ☐ Engineered Fill for Foundation Approved  
☐ Engineered Fill for Slab Approved  
☐ Basement ☐ Garage

**MASONRY FIREPLACE**

- ☐ Throat Inspection Approved

**OTHER INSPECTIONS**

- ☐ Deck Piers Approved

**Inspection Information:**

Inspection Date: 3/22/21

Time On: 4:35pm Time Off: 4:50pm

Was this a reinspection? ☒ Yes ☐ No If Yes, date of the first inspection 3/22/21


COMMENTS FOOTING @ RIGHT REAR CORNER EXCAVATED BELOW GRAVEL POCKET. BEARING ON SOIL.

At the time of this inspection, all items inspected were found to be in conformance with the governing building code.

Certifier Signature:



Phone:



Date:

3/22/21