



April 1, 2021

Summit Homes
120 SE 30th St
Lee's Summit, MO 64082

RE: Inspection for 4400 SW Tanzanite Circle, Lee's Summit, MO– Permit # PRRES20204958

On March 26, 2021, a special inspection was performed by Residential Engineering Services, LLC (R.E.S.) at the above referenced property. The purpose of this inspection was to inspect bores drilled into existing floor joist that measured 2" or less from bottom of joist.

Recommendations:

- RES recommends installing LSTA18 straps under affected joist.

We would like to thank you for the opportunity to consult you on your project. Please feel free to contact us if you have any questions regarding this report or need any further consultation.

Sincerely,

Joshua Elizondo

Joshua Elizondo, Project Engineer

Reviewed by,

Blake Shadid

Blake Shadid, PE

