## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20191614 Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
All Rough Inspection - Commercial		Robb Popp	Partial	Friday, April 02, 2021
Informati 1	onal: THIRD FLOOR	—AREAS APPROVED—		
		***BUIDING C***		
		PRE ROCK: 3019-3031 MECHANICAL F	ROOM WALLS AND BEHIND S	SHOWERS
		ROOMS: 3030, 3028, 3026,	, 3024, 3022, 3020	
		***BUILDING A***		
		PRE ROCK:		
		3003-3016 MECHANICAL F	ROOM WALLS	
		3003-3005, 3009, 3013, 30	15 BEHIND SHOWERS	
Informati	onal:			
2	SECOND FLOOR	—AREAS APPROVED—		
		***BUILDING C***		

		PRE ROCK: OK TO ROCK WALLS OF MECHANICAL ROOMS 2020-2031 OK TO ROCK CORRIDOOR WALLS FOR SOFFIT AND INSTALL RC AT CEILING
Informati 3	onal: FIRST FLOOR	—AREAS APPROVED—
		**MCAL BUILDING**
		PRE ROCK:
Corroctiv	e Action Required:	MECHANICAL ROOM 165 NORTH WALL
4	Miscellaneous Correction	-SEAL CORRIDOOR PENETRATIONS AND DRAFT STOP FOR SOFFIT PRE ROCK -INSTALL RC CHANNEL AT MECHANICAL ROOM CEILINGS AND CORRIDOOR SOFFITS FOR INSPECTION
		*****3-22-21 PRE ROCK AT SHOWERS***** 3012 BOCCA PLATE, 3011 ADD STUD, SEAL PENETRATION AT DWV, AND STRAP TOP PLATE, 3008, BOCCA PLATE, 3007 BOCCA PLATE, STRAP TOP PLATE, 3006 STRAP TOP PLATE,
		-SEAL LINE SET PENETRATIONS IN DRAFT STOP THROUGHOUT-CHECK LINE SET PENETRATIONS AFTER INSTALLATION -3020- MISSING ROOF BOOT AT VENT-CHECK WITH RC INSPECTION

**Comments:**