CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20200599

Informational:

Misc

Address: 3104 SW ARBORIDGE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

concentre delicale nave been completed be not cover any work and approved.				
Inspection:		Inspector:	Outcome:	Date:
DE - Sanitary Sewer Construction Inspection		Tom Taylor	Partial	Monday, July 27, 2020
Informational:				
1	Misc	On Wednesday, 7-08-2020. Redford Construction resumed Sanitary Sewer installation, installing 8" sewer from manhole 1–2 sta.13+36 to18+00. MH—1-3 also was set on line #1. (5) y's were installed for private taps.		
Informational:				
2	Misc	On Thursday, 7-09-2020. Redford Excavating resumed Sanitary Sewer installation. Contractor installed (3) laterals.		
Informational:				
3 Informati	Misc onal:	Contractor resumed placement of the service laterals on Arbor lane dr.		
4	Misc	On Tuesday, 7-14-2020. Redford Excavating resumed installation of the Sanitary Sewer. Installed All remaining Laterals through sta. 18+00.		
Informational:				
5	Misc	On Wednesday, 7-15-2020. Redford Excavating resumed Sanitary Sewer installation. Completed approx. 100 LF of 8" Sewer until rain forced contractor to stop work for the day.		
Informational:				
6	Misc	• •	ford Construction is installind rock fill, they could only p	•

stop working early today because of the heat.

On Thursday, 7-23-2020. Redford Excavating resumed Sanitary Sewer

installation. MH - 5 and approx. 100' of 8" sewer was placed continuing on line 1. Also crew #2 installed Laterial between station 16+40 and 18+70 east side of street.

Informational:

8 Misc On Friday 7-24-2020. Redford Excavating resumed Sanitary Sewer installation

of line #1 and installed MH - 1-6 Lateral lines lines at sta. 21+05, 21+76 and approx. 170 LF of 8" sewer. Crew #2 installaed laterals between sta. 16+00

thru 19+00.

Informational:

9 Misc On Saturday, 7-25-2020. Redford Excavating "s crew #2 finished installing

laterals for line #1. Contractor placed flowable fill over laterals and completed back fill of line #1 before the expected rain Monday!

Informational:

10 Misc On Tuesday, 7-28-2020. Redford worked (2) crews and installed portions of

line #2 and #3. MH 2-1 was installed with approx. 200 LF of 8" sewer line on line #2. Also the contractor installed approx. 100 LF of 8" sewer on line #3.

Comments: