



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20211671, Public Works Right of Way Permit  
Address: 1821 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

|                              |             |          |                          |
|------------------------------|-------------|----------|--------------------------|
| Inspection:                  | Inspector:  | Outcome: | Date:                    |
| <b>Site Visit Inspection</b> | Matt Munger | Partial  | Thursday, April 22, 2021 |

**Corrective Action Required**

|   |      |                                                                                           |
|---|------|-------------------------------------------------------------------------------------------|
| 1 | Misc | Site visit: The area around the ATT box that was installed needs to be properly restored. |
|---|------|-------------------------------------------------------------------------------------------|

**Comments:**