CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20191614

Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Rated Assembly Inspection Robb Popp Partial Friday, April 23, 2021

Informational:

1 THIRD FLOOR -AREAS APPROVED-

BUILDING C

RC CHANNEL MECHANICAL ROOM CEILINGS 3019-3031, CORRIDOOR CEILING SHOWER BUILD OUT CEILINGS 3031,3030,3029,3028,3027,3026,3025,3024,3023,

3022, 3020, 3006, 3007, 3008, 3011, 3012, 3018,

ROCK BEHIND SHOWERS 3019-3031

FIRST LAYER ROOMS 3019-3031 IN BATHROOMS AND LAUNDRY ROOMS

CEILINGS

OK TO INSTALL RC AT CORRIDOOR WALLS

BUILDING B

RC CHANNEL MECHANICAL ROOM CEILINGS 3003-3016 OK TO INSTALL RC CHANNEL CORRIDOOR WALLS FIRST LAYER ROOMS 3003-3016 BATHROOM CEILINGS

BUILDING A

OK TO INSTALL RC CORRIDOOR WALLS AND CEILINGS FIRST 16" EACH SIDE

Informational:

2 SECOND FLOOR -AREAS APPROVED-

BUILDING C:

MECHANICAL ROOM CEILINGS 2019, 2020, 2022, 2024-2031 ROCK BEHIND SHOWERS AT SHEAR WALLS 2019-2031

BUILDING B:

ROCK BEHIND SHOWERS AT SHEAR WALLS 2005,2007,2008,2011-2015

Informational:

3 FIRST FLOOR -AREAS APPROVED-

MCAL BUILDING:

RM 165 NORTH WALL LAYER OVER SHAFT WALL

Corrective Action Required:

4 Miscellaneous

Correction

3021- COMPLETE RIDGE VENT/ ROOF

Comments: