



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20211492, Public Works Right of Way Permit
Address: 1519 SW SUGAR TREE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Passed	Tuesday, April 27, 2021

Corrective Action Required

1 Misc

Site visit: The gas service line has been installed. This is a new home build, so the yard was not established prior to Spires work.

Comments: