



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20211733, Public Works Right of Way Permit  
Address: 4418 SW AMETHYST DR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Partial	Tuesday, April 27, 2021

**Corrective Action Required**

1	Misc	Site visit: The line has not been buried, it is stretching across the yards.
---	------	--

**Comments:**