

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

Permit #:PRPWRW20211664, Public Works Right of Way Permit  
Address: 100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Partial	Wednesday, April 28, 2021

**Corrective Action Required**

1 Misc

Site visit: The J&M crew was onsite working just south of Victoria off Douglas road. I drove from the police station to the hospital and they had utility signs up. They were not working in the road and had pulled off of Douglas. I walked the section south of Victoria to the next road as they had pits open to locate utilities. I informed the crew onsite to make sure and not undercut the sidewalks and to properly compact. I also sent an email to Jim Reed with pictures of restoration that was attempted at the intersection by the police station that needs to be touched up.

**Comments:**