CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRSUBD20202286Address:2020 SW HOOK RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Sanitary Sewer Construction Inspection		John DiMauro	Partial	Thursday, April 22, 2021	
Informational:					
1	Miscellaneous	John DiiMauro witnessed	the core drill and connecti	on to the existing MH.	
	Correction	The contractors have inst out doin g companion tes	alled MH 1-1, 1-2, and 1-3. T it when they backfill.	hey will have a tester	
Informational:					
2	Misc	Contractors have hit rock. Installing pipe fron 1-3 to	. They have installed wyes I 1-4.	between MH 1-2 and 1-3.	
Partial Correction:					
3	Miscellaneous Correction	installed. MH 3-1 has bee	d. The service lines for 55,56 n installed. The service line 1 has 2 sticks of pipe instal	es between 1-3 and 3-1	
Informational:					
4	Miscellaneous Correction	-	stubs and wyes between N Hitting rock so not getting r	-	
Informational:					
5	Misc	still hitting rock. I spoke t condition. Compaction te	rvice line wyes between MI o them about making sure sts are going to be done to in the road over the maiin	the backfill is in good morrow. We will be	
Informational:					

6	Misc	The compaction test have been put off until next Tuesday. They are still hitting rock, installed a few sticks of pipe.		
Informational:				
7	Misc	MH 3-1, 3-2 and the service lines are being installed. They are working on installing the wyes too.		
Informational:				
8	Misc	MH 3-3 has been instlled.All the wyes and service lines has been installed on line 3 up to 3-3. The trench checks and tracer wire has also been installed. Structure 4-1 is not here so they skipped this one.		
Informational:				
9	Misc	On Tuesday, 4-26-2020. Redford Excavating completed laterals for line 33 between MH# 3-3 & 3-4. Crew #2 worked on line #4 install aging MH#4-1 and completed lateral between MH#4-1 and #3-3 and compacted.		

Comments: