

Third Party Inspection Report

Inspector	Date	Time						
David P. Ainsworth, P.E.	5-12-21	2:30 PM						
Company	Permit #	Permit Holder						
David P. Ainsworth, P.E.	2021-1697	SAB Homes						
Inspection Type	Address Monticello Li	ot 147						
FOOTING	4737 NE JAMES	The state of the s						
E-Mail Address dainsworth@chelepis.co								
Instructions: This form must be completed when performing a third party inspection for any building								
permit in Lee's Summit. Submit form	within 48 hours after inspection to t	he Development Services						
Department. If a subsequent inspection	on is performed by the City, this form	n must be submitted prior to						
that inspection being scheduled.								
Check all boxes that apply to the site conditions and the inspection being performed.								
Site Conditions:								
Plans stamped by the City on s	ite with the plot plan included. (Cop	ied plans are not acceptable)						
Erosion controls in place and m	naintained							
*Note: If these requirements are not met no inspection shall be performed or accepted by the City.								
Foundations and Footings:								
Foundation type and MBOE is equal to or above the plot plan								
Concrete encased electrode (ufer) ground installed (Location must be noted in comments)								
Foundation/Footing meets all (engineered design.	City Code requirements and matche	s City approved plans or						
Foundation Walls:								
Elevation is sufficient to achieve	e 2% slope away from structure							
No openings below the MBOE								
Concrete encased electrode (u	fer) ground exposed							
Foundation wall meets all City (engineered design.	Code requirements and matches Cit	y approved plans or						



-							
<u>_</u>	P	2	m	i	P	C	
	ı	a	3 8 8	8	8 8	=	
				_		\circ	~

Framing meets all City Code requirements and matches City approved plans or engineered design.

*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been passed.

Corrective Actions and Comments:

UFER GROUND ROD IS LOCATED ON THE SOUTH SIDEWALL ABOUT IS WEST OF THE SOUTHEAST CORNER.

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both accurate and true.

Signature:

r.t. En

Engineer/Architect Seal