CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20211893 Address: 103 NW JOSHUA DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Erosion Control		Inspector: Michael Harkins	Outcome: Failed	Date: Monday, May 17, 2021
1	DCM2 ESC	DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS		
	DEFICIENT	UNTIL ADEQUATE EROSION CONTROL PROVIDED.		
	INSTALLATION			
		- MAINTAIN SILT FENCI	-	
		- SOIL STOCKPILES SHOULD NOT BE LOCATED NEAR THE STREET, STORM		
		INLETS, LOT ACCESS, OR ADJACENT PROPERTY LINES. ALL STOCKPILES MUST		
		EITHER BE STABILIZED, COVERED, OR HAVE ESC AND BMPs INSTALLED AROUND		
		BASE OF THE PILE -		

Comments: