

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20191614
Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Robb Popp	Partial	Tuesday, May 18, 2021

Informational:
1 THIRD FLOOR

— AREAS APPROVED —

BUILDING C

PRE ROCK:
3019-3031 MECHANICAL ROOM WALLS AND BEHIND SHOWERS

ROOMS: 3019-3031
-STAIRWELL WALLS AND CEILING
CORRIDOR TO SHAFT WALL

BUILDING B

PRE ROCK:
3003-3016 MECHANICAL ROOM WALLS, BEHIND SHOWERS
CORRIDOR TO SHAFT WALL
ROOMS: 3003-3016
STAIRWELL WALLS AND CEILING

BUILDING A*

ROOMS: 3001, 3002, 3017, 3018, 3037, 3038, 3039, 3041, 3042, 3043, 3044, 3045,

Informational:	2	SECOND FLOOR	3047 CORIDOOOR TO SHAFT WALL OK TO INSULATE EXTERIOR WALLS
			—AREAS APPROVED—
Informational:	3	FIRST FLOOR	***BUILDING C*** ROOMS: 2019-2031 CORRIDOR WALLS AND CEILING TO SHAFT WALL ***BUILDING B*** ROOMS: 2003-2017 CORRIDOR WALLS AND CEILINGS TO SHAFT WALL ***BUILDING A*** CORRIDOR CEILINGS TO SHAFT WALL ROOMS: 2001,2002, 2017,2018,2040-2045
			—AREAS APPROVED—
Corrective Action Required:	4	Miscellaneous Correction	***BUILDING C*** CORRIDOR CEILINGS TO SHAFT WALL ***BUILDING B*** CORRIDOR CEILNGS TO SHAFT WALL ***BUIDING A*** CORRIDOR CEILNG TO SHAFT WALL EXTERIOR WALL 1032 OK TO INSULATE **MCAL BUILDING** PRE ROCK: MECHANICAL ROOM 165 NORTH WALL
			-EXPOSE AND SEAL PENETRATIONS AT SHAFT WALL PER UL LISTING *5-17 INSTALL JOIST HANGERS AT ATTIC ACCESS IN CORRIDORS 3040- COMPLETE SPRINKLER INSTALLATION 2035A- FLASH OPENINGS 2047-NOT INSPECTED

Comments: