



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20211911, Public Works Right of Way Permit
Address: 157 NW CARSON DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Partial	Tuesday, May 18, 2021

Corrective Action Required

1	Misc	Site Visit - The service line has to been installed yet.
---	------	--

Comments: