



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPW20212430, Public Works Right of Way Permit
Address: 504 SW 3RD ST, Unit:D, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Partial	Wednesday, May 19, 2021

Corrective Action Required

1	Misc	Site Visit - No workers onsite. They have plywood covering any holes with cones in place.
---	------	---

Comments: